

Set-up procedure for Greenwald-Vertical 4 coin mechanism.

25¢ to \$1.00

- STEP 1 UNHOOK RETURN SPRING (#15)
- STEP 2 PUT COINS IN HANDLE (#12) PUSH HANDLE IN UNTIL COINS DROP THROUGH COIN SLIDE.
- STEPS 3 WHILE HOLDING HANDLE IN. TURN MECHANISM OVER. LOOSEN SCREW (#27) AND REMOVE METAL PLATE (#28) SUPPORTING PLASTIC INSERTS *Note **UP** position stamped on plate before removing.
- STEP 4 REMOVE BLANK PLASTIC INSERT(S) (#24) FROM CAVITY OF COIN HANDLE FOR DESIRED PRICING. (SUGGESTION, SAVE ALL INSERTS FOR FUTURE USE)
- STEP 5 REPLACE METAL PLATE (#28) IN UP POSITION AND RETIGHTEN SCREW (#27)
- STEP 6 RE-ATTACH RETURN SPRING (#15)

